



Overview: Part of spill impact on 14" Okordia-Rumuekpe Pipeline right of way at Imogu. Picture was taken during Joint Investigation of 26th November 2013.



Close-up: Illegal fitting on 14" Okordia-Rumuekpe Pipeline at Imogu. Picture was taken during Joint Investigation of 26th November 2013.