



Overview: Part of spill/fire impact on 28" Bomu – Bonny Pipeline right of way at Kpor/K-dere. Picture was taken during Joint Investigation of 23 rd November 2013.



Close-up: Hacksaw cut on 28" Bomu - Bonny Pipeline at Kpor/K-dere. Picture was taken during Joint Investigation of 23rd November 2013.