



Overview: Part of spill impact on 24" Nkpoku-Bomu Trans Niger Pipeline right of way at Egbalor. Picture was taken during Joint Investigation of 19th November 2013.



Close-up: Illegal fittings on 24" Nkpoku-Bomu Trans Niger Pipeline at Egbalor. Picture was taken during Joint Investigation of 19th November 2013.