



Overview: Part of spill impact on 28" Bomu-Bonny Trans Niger Pipeline right of way at B-dere. Picture was taken during Joint Investigation of 11th November 2013.



Close-up: Illegal fitting on 28" Bomu-Bonny Trans Niger Pipeline at B-dere. Picture was taken during Joint Investigation of 11th November 2013.