



Overview: Part of spill impact on 28" Nkpoku-Bomu Pipeline right of way at Gio. Picture was taken during Joint Investigation of 5th November 2013.



Close-up: Drilled hole/hacksaw cut on 28" Nkpoku-Bomu Pipeline at Gio. Picture was taken during Joint Investigation of 5th November 2013.