




Overview: Part of spill impact on 14" Okordia-Rumuekpe Pipeline at Akaramini. Picture was taken during Joint Investigation of 3rd December 2013.



Close-up: Tampered clamp bolts on 14" Okordia-Rumuekpe Pipeline at Akaramini. Picture was taken during Joint Investigation of 3rd December 2013.



Close-up: Clamp bolts after tightening on 14" Okordia-Rumuekpe Pipeline at Akaramini.
Picture was taken during Joint Investigation of 3rd December 2013.