

THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED.

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1058084 JIV report S/N: 0288

(Note: As practicable as possible the JIT report is to be signed in the field by all the participating parties)

A. GENERAL INFORMATION:

1. Spill incident Number: 1058084 2. Type of incident* OIL SPILL
 3. Name of Location 6" OBIGBO NORTH - EBUBU PIPELINE
 4. Name of nearest community OBOLU 5. State: RIVERS 6. LGA ELEME
 7. Type of Production facility/Installation OIL PIPELINE 8. Asset owner/District PIPELINE

B. INCIDENT INFORMATION:

9. Details of incident

- a. Date of incident: 19TH OCTOBER 2013
 b. Start date/time of investigation: 21ST OCTOBER 2013 / 13:14 HOURS
 c. Investigation End date: 21ST OCTOBER Actual investigation duration, days: ONE (1) DAY
 d. Description of spill point environment 2013

- Firmed soil Loose soil Recently excavated area
NO PIPE COATING OBSERVED NOT TO HAVE BEEN TAMPERED WITH.
 Under water Swampy Exposed pipe surface
 Well Platform (on Water) Drill Rig
- e. Description of leak point (tick as applicable);
- Drilled hole Hack saw cut Tear (____),
 Complete Rupture Inward dent, Well head tampering
 Failed Weld-on illegal hot tap valve, Failed Clamp Missing Pipeline/Flowline
 Crude oil theft (illegal bunkering) point, Third party tampering with Clamp
 Third party tampering with valve setting, Third party tampering with flange,
 Corrosion Saver-pit over flow, Surge vessel overflow,
 Bulging Outward Flare System/Bund wall failure Accidental 3rd party
 equipment impact Valve Failure com unit failure Cold vent
- Relief valve failure Others (specify) _____

f. Incident caused by:

- Third party interference (Sabotage ; crude theft ; Line theft ; Accidental 3rd party damage
 Operational Others (including Mystery spills) _____

g. Spill point coordinates

Measuring unit	
Northing: (m) <u>86736.87</u>	Easting: (m) <u>520530.51</u>

*This can be: a) Oil Spill b) Drilling fluid/Chemical c) Siltation d) construction e) Encroachment f) Fire.

THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED.

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1058084 JIV report S/N: 0288

C. RISK ASSESSMENT

10. Type of environment:

- Land Swamp Water Seasonal swamp Shoreline/Waterfront

i. Type of environment to which oil has spread:

- Land Swamp Water River (identify) _____

ii. Weather condition

- Rain Sunny Dry Wet Windy Hot Cool

11. Distance from the nearest sensitive habitat

- Government reserved and designated protected area [,m]
- Drinking water source [,m]
- Built up area [,m]
- Farmlands [,m]
- Fish Farm/Pond [,m]
- Fishing net [,m]
- Others (specify). **PLAIN TAIN TREES**

PLAIN TAIN TREES IMPACTED BY SPILL

12. Containment measures put in place;

- Booms Trench Dyke Natural depression Pit
 Others: _____

13. Any pictures or video coverage?

[Y] [N]

14. Was there any disruption to the investigation?

[Y] [N]

If yes give brief description:

NOT APPLICABLE

D. TYPE/NUMBERS OF PROPERTIES, IF ANY, FOUND WITHIN THE AREA OF SPREAD OF OIL

15. Structures / Properties

S/N	Type of Structures	Description	Size	Number	Comments
1.	18" X 5" X 8" HIGH SOLID SANDCRETE BLOCKS	SOLID SANDCRETE BLOCKS	18" X 5" X 8"	122 NO.	} WITHIN SPILL - IMPACTED REGION.
2.	SAND HEAP	HEAP CLOSE TO SPILL POINT	1/2 TRIP	NOT APPLICABLE	

16. Crops/Economic Trees

THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED.

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1058084 JIV report S/N: 0288

S/N	Type of crops	Young	Medium	Matured	Quantity	Comments
1.	PLANTAIN	✓ 9	✓ 7	✓ 12	28	} WITHIN SPILL - IMPACTED REGION.
2.	COCONUT			✓ 1	1	
3.	PALM TREE	✓ 1			1	

17. Fish/Nets/Ponds


S/N	Fish/Nets/Ponds	Description	Quantity/Size	Comments
	NONE WITHIN AREA OF IMPACT			

18. Others (Specify) i.e. Animal Traps

S/N	Others	Description	Quantity/Size	Comments
	NONE WITHIN AREA OF IMPACT			

E. GRAPHIC DESCRIPTION OF LEAK POINT (while detail report of the leak point should be contained in the leak report, overview sketch of the site should be added as an appendix 1)

SECTION OF 6" OBLGBO NORTH - EBUBU PIPELINE AT OBOLO SHOWING 2 NO. PINHOLES (DUE TO CORROSION) AT 11 O' CLOCK POSITIONS.



F: TABLE SHOWING SOME OF COORDINATES TAKEN DURING JIV FOR AREA CALCULATION

THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED.

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1058084 JIV report S/N: 0288

Recovered oil V_{rec} :	<u>NIL</u>	Barrels
---------------------------	------------	---------

22. Computation of estimated residual volume on site

a. Computation of estimated volume of pool of free phase oil (on land or confined water body).

- i. Area (m^2) occupied by pool of free phase oil 6
- ii. Average Depth (m) of pool of free phase oil 0.14
- iii. Emulsification factor: NIL

iv.

Estimated Volume of pool of free phase oil. V_{pool} :	<u>5.28</u>	barrels
---	-------------	---------

b. Computation of estimated volume of infiltrated oil in the soil (V_{inf}).

1. Estimated Volume of infiltrated oil at spill point ($V_{inf a}$)

- i. Area* (m^2) of soil covered by the oil: 1
- ii. Average Depth (m) above leaking facility i.e. pipeline/flowline: 1.2
- iii. Soil type: SILT iv. P_e (effective porosity of the soil): 21%
- v. Cause of spill: OPERATIONAL vi. Oil type: BONNY MEDIUM
- vii. Oil Residence time on site, day: 7 DAYS
- viii. Average depth of infiltration below leaking facility i.e. pipeline/flowline: 0.0064m
- ix. Estimated depth of infiltration around spill point: 1.2064m

x.

Estimated Volume of infiltrated oil at spill point. $V_{inf a}$:	<u>1.59</u>	barrels
---	-------------	---------

2. Estimated Volume of infiltrated oil at second spill point [if applicable] ($V_{inf b}$)

- i. Area* (m^2) of soil covered by the oil: _____
- ii. Average Depth (m) above leaking facility i.e. pipeline/flowline: _____
- iii. Soil type: _____ iv. P_e (effective porosity of the soil): _____
- v. Cause of spill: _____ vi. Oil type: _____
- vii. Oil Residence time on site, day: _____
- viii. Average depth of infiltration below leaking facility i.e. pipeline/flowline: _____
- ix. Estimated depth of infiltration around spill point: _____

Estimated Volume of infiltrated oil at spill point. $V_{inf b}$:	<u>NIL</u>	barrels
---	------------	---------

3. E

Estimated Volume of infiltrated oil outside immediate spill point(s) region ($V_{inf c}$)

- i. Area (m^2) of soil covered by the oil: 173
- ii. Area (m^2) of the pool of free phase oil in touch with soil: 4
- iii. Average Depth (m) below ground surface of infiltration of oil: 0.0018m
- iv. Soil type: SILT
- v. P_e (effective porosity of the soil): 21%

vi.

Estimated Volume of infiltrated oil. At $V_{inf c}$:	<u>0.43</u>	barrels
---	-------------	---------

23. Computation of estimated volume of oil on open water based on standard coloration.

- i. Total area of oil on open water: NIL

THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED.

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1058084 JIV report S/N: 0288

- ii. Table of average depth of oil on water based on coloration (**Spill Factors from USCG FOG (2000 Edition))

	Thickness (mm)	Percentage coverage	Volume (m3)
Barely Visible	0.00004	NOT APPLICABLE	
Silvery	0.00008		
Slight Color	0.00015		
Bright Color	0.0003		
Dull	0.001		
Dark	0.002		
Black oil	0.1		
Emulsion (30% Oil)	1		

iii.	Percent Total 100%	Estimated Volume of oil on open water, V _{wat} :	NIL	Barrels
------	--------------------	---	------------	---------

24. Calculation of evaporated volume:

- i. Estimated Volume available for evaporation within surface area: 7.3 BARRELS

- ii. E-Factor: 15%

iii.	Estimated Volume of evaporated oil, V _{evap} :	1.29	Barrels
------	---	-------------	---------

Evaporation Factors (E-Factor) for SPDC Crude oil			
Oil Type	Days on site	Bonny Light	Bonny Medium
Oil Residence time	< 1 day	10%	5%
	1-7 days	25%	15%
	> 7 days	40%	25%

25. Net Estimated Spilled Volume V _{rep} (bbls) = V _{evap} (bbls) + V _{wat} (bbls) + V _{inf} (bbls) + V _{pool} (bbls) + V _{recf} (bbls) = 1.29 + NIL + 2.02 + 5.28 + NIL = 8.59
Estimated Reported Volume** V_{rep}(bbls) = 9 BARRELS

Calculation of the respective estimated volume is to be done on site as far as practicable using the new spill volume estimation software on site; Conversion of m³ to barrels is Volume (m3) x 6.29; **Round up estimated volume to next whole number using the following rules:

- Any spill volume in excess of 1 bbl is rounded up to the next whole number.
- Any spill volume in less than 1 bbl is rounded up to the next 0.1 bbl.

Examples: Calculated volume = 15.3 bbl ----- Reported volume = 16 bbl
 Calculated volume = 0.35 bbl ----- Reported volume = 0.4 bbl
 Calculated volume = 0.01 bbl ----- Reported volume = 0.1 bbl.

Wherever this estimation tool is not applicable please refer to paragraph 6c (Deviations) of the JIV procedure to use appropriate steps for column estimation; record the calculation in a plain sheet of paper and attach to the JIV report.

26. GENERAL STATUS OF THE SITE

A. Joint investigation of the incident site found that there is no residual impact after the initial response and therefore recommend that the site be closed out <input type="checkbox"/>
--

THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED.

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1058084 JIV report S/N: 0288

B. Investigation of the incident site showed that there is residual impact on site requiring further works

27. REPRESENTATIVES

This report was filled, agreed and signed on the 21/10/2013 by joint investigation representatives from

- Host Community:
- Department of Petroleum Resources [DPR]:
- National Oil Spill Detection and Response Agency [NOSDRA]:
- State Ministry of Environment [SME]:
- Nigeria Police Force [NPF]:
- Shell Petroleum Development Company [SPDC]:
- Signatories agree with reported findings:
- Separate DPR form has been filled out with same findings

Tick as applicable

28. Appendix 1: Overview sketch of the site

Location: 6' OBIGBO NORTH - EBUBU PIPELINE AT OBOLD.

