




Overview: Part of spill impact on 6" Obigbo North – Ogale Pipeline right of way at Ogale. Picture was taken during Joint Investigation of 1st November 2013.



Close-up: Spill due to Illegal fitting on 6" Obigbo North – Ogale Pipeline at Ogale. Picture was taken during Joint Investigation of 1st November 2013.