



Overview: Part of spill/fire impact on 24" Nkpoku - Bomu Trans Niger Pipeline right of way at Biara/Kpите. Picture was taken during Joint Investigation of 25<sup>th</sup> October 2013.



Close-up: Hacksaw cut on 24" Nkpoku - Bomu Trans Niger Pipeline at Biara/Kpите. Picture was taken during Joint Investigation of 25<sup>th</sup> October 2013.