



Overview: Part of spill/fire impact on 24" Nkpoku - Bomu Pipeline right of way at Biara. Picture was taken during Joint Investigation of 18th October 2013.



Close-up: Hacksaw cut on 24" Nkpoku - Bomu Pipeline at Biara. Picture was taken during Joint Investigation of 18th October 2013.