



Overview: Parts of spill impact on 14" Okordia - Rumuekpe Pipeline riser at Akinima. Boom in place Picture was taken during Joint Investigation of 16th October 2013.



Close up: Positions of tampered valve and missing nuts & bolts on 14" Okordia - Rumuekpe Pipeline riser at Akinima. Picture was taken during Joint Investigation of 16th October 2013.