



Overview: Part of spill impact on 24" Nkpoku-Bomu pipeline right of way at B-Dere. Picture was taken during Joint Investigation of 10<sup>th</sup> October 2013



Close up: Drilled hole on 24" Nkpoku-Bomu pipeline at B-Dere. Picture was taken during Joint Investigation of 10<sup>th</sup> October 2013.