



Overview: Aerial view of impact from the 24" Nkpoku – Bomu Pipeline spill incident at Nonwa. Picture was taken during overfly assessment of 10<sup>th</sup> October 2013.



Close up: Spill due rupture of 24" Nkpoku – Bomu Pipeline at Nonwa. Picture was taken during Joint Investigation of 13<sup>th</sup> October 2013.