



Overview: Part of spill impact on 36" Rumuekpe-Nkpoku Trans Niger Pipeline right of way at Omuigwe-Aluu. Picture was taken during Joint Investigation of 3rd November 2013.



Close-up: Illegal fittings on 36" Rumuekpe-Nkpoku Trans Niger Pipeline at Omuigwe-Aluu. Picture was taken during Joint Investigation of 7th November 2013.