



Overview: Part of spill impact on 12" Imo River – Ogale Pipeline right of way at Okohia. Picture was taken during Joint Investigation of 30th November 2013.



Close-up: Illegal fittings on 12" Imo River – Ogale Pipeline at Okohia. Picture was taken during Joint Investigation of 30th November 2013.