



**Overview:** Part of spill impact on 20" Otumara-Escravos pipeline at Ogidigben. Picture was taken during Joint Investigation of 19th October 2013.



**Close up:** Spill Points 1 & 2 - Illegal fittings 20m apart on 20" Otumara-Escravos pipeline at Ogidigben. Picture was taken during Joint Investigation of 19th October 2013.