



Overview: Part of spill impact on 20" Otumara-Escravos Pipeline at Ugboegungun.
Picture was taken during Joint Investigation of 19th October 2013.



Close up: Spill due to Illegal fitting on 20" Otumara-Escravos Pipeline at Ugboegungun
Picture was taken during Joint Investigation of 19th October 2013.