



Overview: Part of spill impact on 28" Bomu - Bonny Pipeline at Bodo West Picture was taken during Joint Investigation of 20th September 2013.



Close-up: Spill due to Illegal fitting on 28" Bomu - Bonny Pipeline at Bodo West . Picture was taken during Joint Investigation of 19th September 2013.