



Overview: Spill point within cofferdam on 30" Nembe Creek Pipeline right of way at Krakama. Picture was taken during Joint Investigation of 24th September 2013.



Close up: Illegal fitting on 30" Nembe Creek Pipeline at Krakama. Picture was taken during Joint Investigation of 24th September 2013.