



Overview: Part of spill impact on 24" Nkpoku-Bomu pipeline right of way at BDere. Picture was taken during Joint Investigation of 7<sup>th</sup> September 2013.



Close up: Drilled hole on 24" Nkpoku-Bomu pipeline at BDere. Picture was taken during Joint Investigation of 7<sup>th</sup> September 2013.