



Overview: Part of spill impact on 12" Imo River1 – Ogale pipeline right of way at Umuololo/Owaza. Picture was taken during Joint Investigation of 19<sup>th</sup> September 2013.



Close up: Illegal fitting on 12" Imo River1 – Ogale pipeline at Umuololo/Owaza. Picture was taken during Joint Investigation of 19<sup>th</sup> September 2013.