



Overview: Part of spill impact on 24" Bomu-Bonny Trans Niger Pipeline right of way at Okolo Launch. Picture was taken during Joint Investigation of 28th September 2013.



Close up: Illegal fittings on 24" Bomu-Bonny Trans Niger Pipeline at Okolo Launch. Picture was taken during Joint Investigation of 28th September 2013.