



Overview: Part of spill impact on 28" Bomu-Bonny pipeline right of way at Oloma. Picture was taken during Joint Investigation of 25<sup>th</sup> September 2013.



Close up: Illegal fittings on 28" Bomu-Bonny pipeline at Oloma. Picture was taken during Joint Investigation of 25<sup>th</sup> September 2013.