



Close up: Hacksaw cut on 4" Ubie Well 5L flowline at Idu Ekpeye. Picture was taken during Joint Investigation of 26th September 2013.