




Overview: Part of spill impact on 36" Nkpoku-Bomu Pipeline Right of Way at Atali. Picture was taken during Joint Investigation of 23rd April 2014.



Close-up: Illegal fittings on 36" Nkpoku-Bomu Pipeline at Atali. Picture was taken during Joint Investigation of 23rd April 2014.