



Overview: Oil stained palm trees on 4" Nun River Well10T Flowline Right of Way at Oporoma. Picture was taken during Joint Investigation of 29<sup>th</sup> April 2014.



Close-up: Hacksaw cut on 4" Nun River Well10T Flowline at Oporoma. Picture was taken during Joint Investigation of 29<sup>th</sup> April 2014.