




Overview: Spill impact on Nembe1 Well35L Flowline Right of Way at Nembe Creek. Picture was taken during Joint Investigation of 15th April 2014.



Close-up: Drilled hole on Nembe1 Well35L Flowline at Nembe Creek. Picture was taken during Joint Investigation of 15th April 2014.