




Overview: Part of spill impact on KoloCreek Well 3T Flowline right of way at Otusega. Picture was taken during Joint Investigation of 7th April 2014.



Close-up: Hacksaw cut on KoloCreek Well 3T Flowline at Otusega. Picture was taken during Joint Investigation of 7th April 2014.