



Close-up: Illegal fitting (spill point) on 28" Bomu-Bonny Pipeline at Oloma. Picture was taken during Joint Investigation of 26<sup>th</sup> November 2014.



Close-up: Illegal fitting (non-leaking) on 28" Bomu-Bonny Pipeline at Oloma. Picture was taken during Joint Investigation of 26<sup>th</sup> November 2014.