




Overview: Part of spill impact on 8" Obigbo North - New Eelenwo at Umukolobe .
Picture was taken during Joint Investigation of 10th August 2014.



Close-up: Illegal fittings on 8" Obigbo North - New Eelenwo at Umukolobe . Picture was taken during Joint Investigation of 9th August 2014.