



Overview: Part of spill impact 12" Imo River – Ogale Pipeline at Komkom . Picture was taken during Joint Investigation of 12th August 2014.



Close-up: Illegal fitting on 12" Imo River – Ogale Pipeline at Komkom . Picture was taken during Joint Investigation of 12th August 2014.