



**Overview:** Part of spill impact on 12" Imo River – Ogale Pipeline at Komkom . Picture was taken during Joint Investigation of 12<sup>th</sup> August 2014.



**Close-up:** Illegal fittings on 12" Imo River – Ogale Pipeline at Komkom . Picture was taken during Joint Investigation of 12<sup>th</sup> August 2014.