THE SHEEL PETROLLOW DEVELOPMENT COMPANY OF MIGHTA LIMITED.
JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1126447 JIV report \$/N:
(Note: As practicable as possible the JIT report is to be signed in the field by all the participating parties)
A. GENERAL INFORMATION:
1. Spill incident Number: 1126447 2. Type of incident* OLL SPILL
3. Name of Location OPUKUSHI WELL - 9T FLOWLINE
4. Name of nearest community EGBEMO-ANGALABIR S. State: BAYELSA 6. LGA EKEREMOR
7. Type of Production facility/Installation FLOWLINE 8. Asset owner/District SWAMP 2
B. INCIDENT INFORMATION:
9. Details of incident a. Date of incident: 21 FEBRUARY 2014 b. Start date/time of investigation 22ND FEBRUARY 2014 AT 1345HRS c. Investigation End date: 22ND FEB. 2014 Actual investigation duration, days: 1 DAY d. Description of spill point environment
Firmed soil
☐ Under water ☐ Swampy ☐ Exposed pipe surface
□Well Platform (on Water) □Drill Rig
e. Description of leak point (tick as applicable); ☐ Drilled hole ☐ Hack saw cut ☐ Tear (
_ ` ` ` _
☐ Crude oil theft (illegal bunkering) point, ☐ Third party tampering with Clamp
☐ Third party tampering with valve setting, ☐ Third party tampering with flange, ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐
Corrosion Saver-pit over flow, Surge vessel overflow,
Bulging Outward
impact
f. Incident caused by:
☐Third party interference (Sabotage□; crude theft□; Line theft□; Accidental 3 ^{at} party damage□)
☐Others (including Mystery spills)
g. Spill point coordinates Measuring unit METEAS MINNA (WEST-BELT)
Northing: Easting:
100992 MN 371544 ME

					IPANY OF NIGE		
JOINT INV	ESTIGATION RI	EPORT FOR INC	IDENT NO:	11264	147JIV report	s/n: 0232	
C. RI	SK ASSESSME	NT					
	10. Type	of environment:					
	□Land	⊠ Swamp	□Water	□Scas	onal swamp□Shor	eline/Waterfront	
	і. Туре с	of environment to w	hich oil has	spread:			
	□Land	⊠ Swamp	□Water	□Rive	r (identify)		
	ii. Weath	er condition					
1:	☐Rain 1. Distance from t	Sunny the nearest sensitive	□Dry habitat	□Wet	•	□Hot □cool	
	☐ Government ☐ Drinking w ☐ Built up and ☐ Farmlands ☐ Fish Farm/ ☐ Fishing net ☐ Others (spe	ea Pond t	gnated prote	ected area	[m, m] [m	NONE SEEN THE VICINI	WIAHI TY
13	2. Containment m	easures put in place	: ;				
	□Booms □Others:	☐Trench	⊠Dyke	□Natı	ral depression	☑ Pit	
1	3. Any pictures or	r video coverage?			(N)		
1	4. Was there any	disruption to the inv	vestigation?		[Y] [V]		
If yes	give brief descript	tion:		APPL	I CAB [_E	_
	<u> </u>	 					_
	YPE/NUMBERS 5. Structures / P.		5, IF ANY, 1	FOUND WIT	HIN THE AREA O	F SPREAD OF OIL	_
S/N	Type of Struct	ures Descrip	tion Size	Nun	nber	Comments	
	LIONE	- LAN TH 12	LAR1	A OF	= IMPAC		

Type of Structures	Description	Size	Number	Comments
<u> </u>	<u> </u>		- 	<u> </u>
LICATE LUI	7411	DEA	10F IMPAC	7
Mar-Mar-	 [1 100-		
	 		<u> </u>	
			-	
	LICATE LUI	LICATE LITTURAL	LICALE LUTTUAL ADEA	LIONE LUTHIN AREA OF IMPAC

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1126447 JIV report S/N:

			i — —	1 1
	·			1
	l t		!	!
	6 Canallanamia Trope			
	Crops/Economic Trees			
•	0. 0.0pa_0			

S/N	Type of crops	Young	Medium	Matured	Quantity	Comments
	HARD WOOD			19	19	
2	OIL PALM	1	14	30	55	
3	RAFFIA PALM		20	18	38	<u>/</u>
4	PLANTAIN	<u> </u>	2	<u> </u>	<u> &</u>	
				<u> </u>		
				<u> </u>		

17. Fish/Nets/Ponds


S/N	Fish/Nets/Ponds	Description	Quantity/Size	Comments
				Λ -
	11011= 1-1	THI AREA	OF M	PACT
<u> </u>	700AC MI	711 (70 7.70		
		<u> </u>		

18. Others (Specify) i.e. Animal Traps

S/N	Others	Description	Quantity/Size	Comments
			-ne-h	h 10 1-2-7-
-	MUNIT M	THIN TRACT	<u> </u>	METT -
				

E. GRAPHIC DESCRIPTION OF LEAK POINT (while detail report of the leak point should be contained in the leak report, overview sketch of the site should be added as an appendix 1)

ACCIDENTAL FLOWLINE DAMAGE (TEAR) AT 3 O'CLOCK POSITION



OPUKUSHI WELL-9T FLOWLINE AT EGBEMO-ANGALABIRI Page 3 of 9

THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMTED. JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1126447 JIV report S/N: 0232

F: TABLE SHOWING SOME OF COORDINATES TAKEN DURING JIV FOR AREA CALCULATION

19. Impacted area boundary Coordinates (If more, Print and attach as an appendix)

MINIA (LIECT - BELT)

	MINNA (WEST	- BELT)
S/N	Northing (m)	Easting (m)
<u>l</u> ·	100987	371550
2.	100983	371544
3.	100964	371553
4	100956	34/563
4	100965	371577
6.	100969	391579
7.	100978	371588
8· 9 ·	100979	371560
9.	100990	371542
10.	100992	371537
11-	100971	371491
12.	100965	371489
12.	100997	371534
14.	100994	371536
15.	100996	371539 371538
16.	101000	371538
14.	100787	371534
_ 18.	106999	371537
19.	100984	371556
20:	100980	371575
! 		
1		-

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1126447 JIV report S/N: 0232

INVESTIGATION REPORT FOR INCIDENT NO: 1126 T 1 JIV report 5/N; 0202	
G. INCIDENT INFORMATION:	
20. Impacted Area Details	
 Total calculated area of impact	
• Impact within SPDC R.O.W 714 M ²	
• Impact outside SPDC R.O.W 304 m ²	
21. Volume of oil recovered before completion of JIV (V _{reel}):	
Recovered oil V _{rees} : NIL Barrels	
22. Computation of estimated residual volume on site	
a. Computation of estimated volume of pool of free phase oil (on land or confined water body). i. Area (m²) occupied by pool of free phase oil	
ii. Average Depth (m) of pool of free phase oil 0 · 0 m	
iii. Emulsification factor: 20 %	
iv. Estimated Volume of pool of free phase oil. V _{pool} : 6.9 barrels	
 b. Computation of estimated volume of infiltrated oil in the soil (V_{int}). 1. Estimated Volume of infiltrated oil at spill point (Vinf a) 	
i. Area* (m²) of soil covered by the oil:	
ii. Average Depth (m) above leaking facility i.e. pipeline/flowline: 0 • 3 M	
iii. Soil type: LATERITE iv. P_e (effective porosity of the soil). 2.0 $^{\circ}/_{\text{D}}$	
v. Cause of spill: OFERATIONAL vi. Oil type: BONNY MEDIUM	
vii. Oil Residence time on site, day: 1 DKY	
viii. Average depth of infiltration below leaking facility i.e. pipeline/flowline: 0 . 50 64 p	1
ix. Estimated depth of infiltration around spill point: D-3064 M	
Estimated Volume of infiltrated oil at spill point. V _{inf_a} : 1.54 bar	rels
2. Estimated Volume of infiltrated oil at second spill point [if applicable] (Vinf b)	
i. Area* (m³) of soil covered by the oil:	
ii. Average Depth (m) above leaking facility i empeline/flowline:	
iii. Soil type: iv. Pe (effective porosity of the soil)	
v. Cause of spill:	
vii. Oil Residence time on site, day, \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	
viii. Average depth of infiltration below leaking facility i.e. pipeline/flowline:	
ix. Estimated depth of incitration around spill point:	
Estimated Volume of infiltrated oil at spill point. V _{inf.b} :	

3. Estimated Volume of infiltrated oil outside immediate spill point(s) region (Vinf c)

OINT INVESTIGATION REPORT FOR INCIDENT NO: 1126 447 JIV report S/N:										
i. Area (m2) of soil covered by the oil: 630 m ²										
i. Area (m2) of soil covered by the oil: $\frac{830 \text{ m}^2}{1000000000000000000000000000000000000$										
iii. Average Depth (m) below ground surface of infiltration of oil: 0 · 000 9 M										
	a marine									
	20 %									
v. P _c (effective porosity of the soil). 20 10 vi. Estimated Volume of infiltrated oil. At V _{inf} : 0.72 barrels										
										
23. Computation	of estimated vo	olume of oil on c	pen water base	d on stand	dard coloration.					
		ter: NOT A								
ii. <u>Table of av</u>	verage depth ot_o	il on water based	on coloration (**Spill l Edition)	Factors from USCG	FOG (2000				
	Thickness	Percentage								
	(mm)	coverage	Volume (m3))		•				
Barely Visible	0.00004		/							
Silvery	0.00008		90	_						
Slight Color	0.00015		<u> </u>							
Bright Color	:			-						
Dull	0.001			-						
Dark	0.002			┪						
Black oil	0.1	 (6),	<u> </u>	-						
Emulsion (30% Oil)	1	4								
 [Percent Total Ferimated Volu	me of oil on open	water V .		Lu Ba	rreis				
iii.		-			J{L Ba					
24. Calculation of					10 15	ماده				
i. Estin	nated Volume a	vailable for eva	poration within	surface a	rea: 19 . +	BBLS				
ii. E-Fa	ctor: <u>15 7</u> .	<u> </u>								
iii.	EstimatedVo	olume of evaporat	ted oil. V _{evap} :	3	.38 Ba	irrels				
Evan	oration Factors	(E-Factor) for S	PDC Crude oil		 1					
Oil Type	Days on site	Bonny Light	Bonny Me							
Oil Residence time	< I day	10%		5%						
	1-7 days	25%		15%						
	>7 days	40%	<u> </u>	25%						
25 Not Felimot	ed Spilled Vol	uma V. (hbls)	- V (bble)	⊥ V (b)	hle) + V. (bble)	дV .				
(bbls) + V _{rec}	25. Net Estimated Spilled Volume $V_{\text{gsl}}(\text{bbls}) = V_{\text{evap}}(\text{bbls}) + V_{\text{wat}}(\text{bbls}) + V_{\text{inf}}(\text{bbls}) + V_{\text{pool}}(\text{bbls}) + V_{\text{recl}}(\text{bbls}) = 3.38 + 2.27 + 16.91 = 22.56 BBLS$									
Estimated Reported V	Estimated Reported Volume** V _{rep} (bbls)= 23 BBLS									
l <u></u>	25 8615									

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1126 447 JIV report S/N: 0232

Calculation of the respective estimated volume is to be done on site as far as practicable using the new spill volume estimation software on site; Conversion of m^3 to barrels is Volume (m3) x 6.29; **Round up estimated volume to next whole number using the following rules:

- Any spill volume in excess of -1 bbl is rounded up to the next whole number.
- Any spill volume in less than I bbl is rounded up to the next 0.1 bbl.

Examples:

Calculated volume = 15.3 bbl ------ Reported volume = 16 bbl Calculated volume = 0.35 bbl ------ Reported volume = 0.4 bbl

Calculated volume = 0.01 bbl ----- Reported volume = 0.1 bbl.

Wherever this estimation tool is not applicable please refer to paragraph 6c (Deviations) of the JIV procedure to use appropriate steps for column estimation; record the calculation in a plain sheet of paper and attach to the JIV report.

26. GENERAL STATUS OF THE SITE

- A. Joint investigation of the incident site found that there is no residual impact after the initial response and therefore recommend that the site be closed out
 - B. Investigation of the incident site showed that there is residual impact on site requiring further works

27. REPRESENTATIVES

This report was filled, agreed and signed on the $22/\sqrt{02}/20\sqrt{4}$ by joint investigation representatives from

- Host Community:
- Department of Petroleum Resources [DPR]:
- National Oil Spill Detection and Response Agency [NOSDRA]:
- State Ministry of Environment [SME]: ☑
- Nigeria Police Force [NPF]: ☑
- Signatories agree with reported findings: □
- Separate DPR form has been filled out with same findings

Tick as applicable

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1126447 JIV report S/N: 0232

28. Appendix 1: Overview sketch of the site

