



Overview: Part of spill impact on 28" Nkpoku-Bomu Pipeline right of way at Ekporo. Picture was taken during Joint Investigation of 19th January 2014.



Closeup: Illegal fitting on 28" Nkpoku-Bomu Pipeline right of way at Ekporo. Picture was taken during Joint Investigation of 19th January 2014.



Overview: Part of spill impact on 28" Nkpoku-Bomu Pipeline right of way at Ekporo. Picture was taken during Joint Investigation of 19th January 2014.



Close-up: Illegal fitting on 28" Nkpoku-Bomu Pipeline at Ekporo. Picture was taken during Joint Investigation of 19th January 2014.



Overview: Part of spill impact on 28" Nkpoku-Bomu Pipeline right of way at Ekporo. Picture was taken during Joint Investigation of 21st January 2014.



Close-up: Illegal fitting on 28" Nkpoku-Bomu Pipeline at Ekporo. Picture was taken during Joint Investigation of 21st January 2014.