



Overview: Part of spill impact on Santa Barbara Well6T Flowline right of way at Ikegimakiri. Picture was taken during Joint Investigation of 8th January 2014.



Close-up: Illegal fitting on Santa Barbara Well6T Flowline at Ikegimakiri. Picture was taken during Joint Investigation of 8th January 2014.