



Overview: Part of spill impact on 20" Otumara-Escravos Pipeline right of way at Ugboegun. Picture was taken during Joint Investigation of 31st January 2014.



Close-up: Non-leaking illegal fitting on 20" Otumara-Escravos Pipeline at Ugboegun. Picture was taken during Joint Investigation of 31<sup>st</sup> January 2014.



Close-up: Leaking illegal fitting on 20" Otumara-Escravos Pipeline at Ugboegungun.  
Picture was taken during Joint Investigation of 31<sup>st</sup> January 2014.