



Overview: Part of spill impact on 28" Nkpoku-Bomu Pipeline right of way at Ekporo. Picture was taken during Joint Investigation of 20th January 2014.



Close-up: Illegal fitting on 28" Nkpoku-Bomu Pipeline at Ekporo. Picture was taken during Joint Investigation of 20th January 2014.