



Overview: Part of spill impact on 30" Nembe Creek Pipeline right of way at Elem-Kalabari. Picture was taken during overfly of 26th January 2014.



Close-up: Illegal fitting on 30" Nembe Creek Pipeline at Elem-Kalabari. Picture was taken during Joint Investigation of 28<sup>th</sup> January 2014.