



Overview: Part of spill impact 28" Nkpoku-Bomu Pipeline right of way at Kporghor. Picture was taken during Joint Investigation of 19th January 2014.



Close-up: Illegal fitting on 28" Nkpoku-Bomu Pipeline at Kporghor. Picture was taken during Joint Investigation of 19th January 2014.