



Overview: Part of spill impact on 20" Opukushi – Brass Creek Pipeline right of way at Tamogbene. Picture was taken during Joint Investigation of 27th January 2014.



Close-up: Illegal fitting on 20" Opukushi – Brass Creek Pipeline at Tamogbene. Picture was taken during Joint Investigation of 27th January 2014.