



Overview: Part of spill impact on 24" Nkpoku-Bomu Pipeline right of way at B-Dere. Picture was taken during Joint Investigation of 17th January 2014.



Close-up: Drilled hole on 24" Nkpoku-Bomu Pipeline at B-Dere. Picture was taken during Joint Investigation of 17th January 2014.