



Overview: Part of spill impact on Okordia Manifold right of way at Ikarama/Okordia. Picture was taken during Joint Investigation of 1st February 2014.



Close-up: Tampered valve on Okordia Manifold at Ikarama/Okordia. Picture was taken during Joint Investigation of 1st February 2014.