Overview: Part of spill impact on 8" Umuechem – Nkpoku Pipeline Right of Way at Omunwei. Picture was taken during Joint Investigation of 3rd July 2014

Close-up: Illegal fitting on 8" Umuechem – Nkpoku Pipeline at Omunwei. Picture was taken during Joint Investigation of 3rd July 2014