



Overview: Part of spill impact on 20" Otumara – Escravos Pipeline Right of Way at Ugboegungun. Picture was taken during Joint Investigation of 4th June 2014.



Close-up: Illegal fitting on 20" Otumara – Escravos Pipeline ta Ugboegungun. Picture was taken during Joint Investigation of 4th June 2014.