



6/5/2014 3:20:48 PM (+2.0 hrs) Lat=4.99932 Lon=5.67404 Alt=3ft MSL WGS 84

Overview: Part of spill impact on Benisede – Brass Creek Pipeline Right of Way at Ojobo. Picture was taken during Joint Investigation of 5th June 2014.



6/5/2014 4:05:11 PM (+2.0 hrs) Lat=4.99926 Lon=5.67409 Alt=46ft MSL WGS 84

Close-up: Illegal fitting on Benisede – Brass Creek Pipeline at Ojobo. Picture was taken during Joint Investigation of 5th June 2014.