




Overview: Part of spill impact on 20" Opukushi-Brass Creek Pipeline Right of Way at Tamogbene. Picture was taken during Joint Investigation of 14th June 2014.



Close-up: Illegal fitting on 20" Opukushi-Brass Creek Pipeline at Tamogbene. Picture was taken during Joint Investigation of 14th June 2014.