



Overview: Oil stains on concrete surface at Santa Barbara Mobile Production Facility. Picture was taken during Joint Investigation of 10<sup>th</sup> June 2014.



Close-up: Cover of closed drain at Santa Barbara Mobile Production Facility. Picture was taken during Joint Investigation of 10<sup>th</sup> June 2014.