



Overview: Spill clearly visible after excavation on 36" Nkpoku-Bomu Pipeline at Atali. Picture was taken during Joint Investigation of 6th June 2014.



Close-up: Illegal fittings on 36" Nkpoku-Bomu Pipeline at Atali. Picture was taken during Joint Investigation of 6th June 2014.