



Overview: Oil sheen observed on Belema Well2T Wellhead Right of Way at Belema. Picture was taken during Joint Investigation of 13<sup>th</sup> June 2014.



Close-up: Control unit missing from Belema Well2T Wellhead at Belema. Picture was taken during Joint Investigation of 13<sup>th</sup> June 2014.