



Overview: Oil sheen observed on Belema Well7L Wellhead Right of Way at Belema. Picture was taken during Joint Investigation of 27<sup>th</sup> June 2014.



Close-up: Former position of Control unit removed from Belema Well9T Wellhead at Belema. Picture was taken during Joint Investigation of 27<sup>th</sup> June 2014